



Product Service

# Verification Report


according to Directive 98/79/EC Annex IV.6

Add value.  
Inspire trust.

**No.** ROC-04687787 23 08 064461

**Manufacturer:** **ROCHE Diagnostics GmbH**  
Sandhofer Strasse 116  
D-68305 Mannheim

**Product:** **Elecsys HBsAg II**

Mat-Nr.: 08814848190  
HBsAg G2 Elecsys E2G 300  
Batch: 73003501  
2° 8°C   
Lot: 040002523787 24.07.2023  
Sample No./Type: 201575828/Y2

**Batch:** **73003501**

**Expiry Date:** **31.03.2025**

The above mentioned batch meets the batch release criteria established during design examination and may be placed on the market. The design examination certificate issued for this product is V7 010283 0610 Rev. 05.

P/N 08814848190

**Date,** 2023-08-03

*Matilde C.V. Nagel*

Adobe Acrobat Sign-Transaktionsnummer: CBJCHBCAABAAPhwzXEZ\_CdNIACS1R50KffbrgHIGBRMg

i.A. Dr. Matilde Calado Vieira Nagel  
In-vitro Diagnostics

TÜV SÜD Product Service GmbH is Notified Body according to Council Directive 98/79/EC concerning In-vitro Diagnostic Medical Devices with Identification No. 0123.

**To:**  
ROCHE Diagnostics GmbH  
Dr. Sonja Leyrer  
+49 8856 6016175

cc: PEI-IVD, FAX +49 6103 77123

Headquarters: Munich  
Trade Register Munich HRB 85742  
V.A.T. DE 129484267  
UniCredit Bank AG - BIC HYVEDEMMXXX  
IBAN DE13 7002 0270 0048 8522 11  
Information pursuant to § 2 [1] DL-InfoV

Supervisory Board:  
Holger Lindner (Chairman)  
Board of Management:  
Walter Reithmaier (CEO)

Tel.: +49 89 50084-483  
Fax: +49 89 50084-475  
[www.tuvsud.com/ps](http://www.tuvsud.com/ps)

TÜV SÜD Product Service GmbH  
In-vitro Diagnostics  
Ridlerstrasse 65  
80339 München